

Post War, M40 Built for Police Dept.

*

- Early Rem 700 Action which was not clip slotted but was cut for thumb relief. *
- Barrel is M40 Barrel with proper taper, correct rifling, and correct crown
- Barrel has 2 sets of proofs. Barrel has original Rem proofs and date codes @ 12 & 6 o'clock position from where it indexed originally. A second set was added @ 9 & 3 o'clock when it indexed differently when rebuilt on this receiver.
- Stock is ^{correct} M40 and is re-numbered to the receiver in barrel channel.
- Stock ^{all} was bedded properly to action
- stock was DOD stamped
- Butt plate is correct and ~~has~~ stock has ^{assembly} numbers stamped on it under butt plate
- Barrel is free-floated
- The bolt is electro penciled with matching serial # on bottom of bolt.
- The trigger group is correct ^{early} split sear type
- The bolt shroud is correct ^{early} short-type
- The safety is correct, early type

Rebuilt M40 (Cont)

- The sling swivels are correct M40 type.
- The scope base is correct 40X Marked early type
- The rings ^{bottoms} are marked 1-64 on the bottom and were numbered 1 and 2 after they were lapped/fit to the scope. The previous owner lost the tops after removing the scope. The replacement tops ~~are~~ are the correct vintage and type + DATE.

(~~the~~) The scope is a correct ^{1st Gen} Redfield 3-9 power Accurange scope. It is the original anodized green color. The range finding "tombstone" has come loose and ~~is~~ we assume is floating around in the scope. This is common as the glue holding it would melt if exposed to hot sunlight common in Southeast Asia.

- The whole gun minus scope was re-parkerized

- The barrel, action, ^{scope} base, ^{and} rings were all reparkerized apparently at the same time as the color matches and is a green color known to come out of Quantico in the 1970's. This is a color nearly impossible

Conto

- 3 -

to duplicate today.

- The trigger guard and floorplate are correct M40^{type}
- This rifle appears to have been built out of salvaged M40 parts post Vietnam. The scope was renumbered to this receiver. You can see where the previous serial # was lightly ground off, taped off, painted black, then electro penciled with the proper number. The stock has the serial number in the barrel channel and you can see where there are remnants of the old serial # underneath the new one. The barrel has two sets of proofs; this was due to it indexing differently in 2 dif. receivers. The bott, receiver, and optics base + rings have not been renumbered. They were likely new replacement parts WHEN REBUILT.

* THIS GUN IS VERY LOW SERIAL RANGE FOR M40s. MOST KNOWN M40 ARE IN 220,XXX range; THIS ONE IS 214,XXX. WE THINK THIS EXPLAINS WHY THIS RECEIVER DOES NOT HAVE CLIP SLOT.

ALSO, REMINGTON ARMS DOES NOT HAVE RECORD OF THIS SERIAL NUMBER, WHICH IS PROPER FOR GOV. CONTRACTS.

SHIPPING CONTAINER TALLY						Express Station BYNUM, ALABAMA		REQUISITION AND INVOICE / SHIPPING DOCUMENT (EAM)																																													
ANNISTON ORDNANCE DEPOT ANNISTON, ALABAMA						MAIL ADDRESS		REQUISITION NUMBER OR AUTHORITY		6. PRIORITY		7. REQUISITION DATE		8. BULKWAY, RQD.		9. VOUCHER DATE		10. VOUCHER NUMBER																																			
Oliver Springs Police Dept. 607 Easterbrook Ave						57410 0000000000000000																																															
Sgt. G.D. Branham																																																					
ACCOUNTING AND FUNDING DATA						911 H ACCOUNT 97		CONDITION CODE 6		SERVICEABLE		CONVERSION		EXPRESS RECPT # 32116																																							
FEDERAL STOCK NUMBER, DESCRIPTION, AND CODING OF MATERIAL AND/OR SERVICES						UNIT WEIGHT		UNIT CUBE		BRIE LOT ISSUE		TYPE CON-TAINER		CON-TAINER NO.		QUANTITY REQUESTED		SUPPLY ACTION		UNIT PRICE		TOTAL COST																															
						DOLLARS		CENTS		DOLLARS		CENTS																																									
01000 1005-673-7955 71101 6 6 B 97 911																																																					
Rifle, cal. 7.62 M40																																																					
SERIAL NR: 214631						AUTH: AR 700-100 \$		PAID		N/A																																											
THIS AMOUNT COVERS THE COST OF THE ITEM AS WELL AS THE PACKING & HANDLING																																																					
THIS DOCUMENT CONSTITUTES A BILL OF SALE AND IS EVIDENCE OF LAWFUL TRANSFER OF TITLE FROM THE GOVERNMENT OF THE UNITED STATES TO PERSON WHOSE NAME APPEARS ABOVE. LACK OF SUFFICIENT EVIDENCE OF TRANSFER OF TITLE COULD RESULT IN CONFISCATION OF FIREARM DESCRIBED ABOVE UNDER PROVISIONS OF RS USC 10-1317. THIS SALE IS RECORDED AT THE U. S. ARMY ORDNANCE, MAJOR ITEM SUPPLY MANAGEMENT AGENCY, CHAMBERSBURG, PA. IN THE EVENT OF LOSS OR ANY OTHER DISPOSITION THE MAJOR ITEM SUPPLY MANAGEMENT AGENCY, CHAMBERSBURG, PA. SHOULD BE NOTIFIED. SALE IS FINAL AND THE U. S. GOVERNMENT RETAINS NO OBLIGATION OR RESPONSIBILITY FOR MALFUNCTION, REPAIR, REPLACEMENT OR EXCHANGE.																																																					
TRANSPORTATION VIA MATS						OR MSIS CHARGEABLE TO						TOTAL WEIGHT						TOTAL CUBE						CONTAINERS RECEIVED EXCEPT AS NOTED						DATE						BY						GRAND TOTAL											
ISSUED BY						CHECKED BY						PACKED BY						DESCRIPTION						13						FIREARMS						1						OTH						21. RECEIVER'S VOUCHER NUMBER					